(3 Hours)

[Total Marks: 80]

(2) (3)	Assum Conce	ion No.1 is compulsory and Answer 3 Questions remaining 5 Questions.  The suitable data wherever necessary pts explanation with suitable case study justification and sketches explanations are right to reserve full marks	
Q1	Answer Any Four Questions		9 6 6 9 6 7
	a)	Write a short note on Nano Metrology.	20
	b)	Explain Eddy current testing methods.	100 S
	c)	Write a note on CMM and enlist its types.	Z Z Z
	d)	Explain Surface irregularities with sketches measuring parameters R <sub>a</sub> , R <sub>z</sub> , R <sub>y</sub> and RMS.	3087
	e)	What is Metrology? Explain different types of standards.	
Q2	a)	Derive an expression for determination of effective diameter of threads by using two wire method.	10
	b)	Define Interferometry. Explain Laser Interferometer with neat sketch.	10
Q3	a)	Explain the floating carriage micrometer with principle, construction, and measurement of threads.	10
ŲJ	b)	Explain Significance of Quality & Quality Control in Industries with suitable examples.	10
Q4	a)	Explain the pneumatic comparator with principle, construction, and operation in detail.	10
	b)	Explain various SQC Tools in quality engineering in detail.	10
Q5	a)	Calculate the limits, tolerances, and allowances on a 25 mm shaft and hole pair designated H7/g6 to get a precision fit. The fundamental tolerance is calculated by the following equation: $i = 0.453 \ 3 \ D + 0.001D$ The following data is given:  (i) Upper deviation of shaft = $-2.5D^{0.34}$	10
		(ii) 25 mm falls in the diameter step of 18–30 mm (iii) IT7 = 16i (iv) IT6 = 10i (v) Wear allowance = 10% of gauge tolerance.	
	b) Explain the Parkinson Gear Tester with sketches in Gear profile checking process.		10
Q6	Answer Any Two Questions		20
	(b)	Explain Autocollimator with sketches and its working principle in detail.  What is acceptance sampling? Explain OC Curve in detail.  Explain in detail - Design of GO and NO-GO gauges procedure with diagram.	
135 S	7 2 2 3		

**Instructions:**